






Exterior Finishes		
1	Roof	Natural Wood
2	Brick	Acme - Kennewick
3	Stone	Rockdale Stone – Titan Gray – White Mortar
4	Stucco	Dryvit – Brite White
5	Shutters Front Door	KM4792 Fern Gully
6	Trim & Garage Door	KM5771 Apple Hill
7	Stain	Storm System – dark oak
8	Front Porch Light	Dement
9	Door Handle Set	Collected


COLLECTED



Overall Finishes

1	Walls & Ceiling	KM5819 Rotunda White
2	Trim & Cabinets (unless otherwise noted)	KMW46 Picket Fence
3	Stain	Dark walnut
4	Vinyl Plank	Armstrong - Driftwood
5	Carpet	Shaw – Ride It Out - taupestone
6	Bedroom Fans	Dement
7	Interior Door Hardware	Collected


COLLECTED



Back Patio

1	Back Patio Fan	Dement
---	-------------------	--------


COLLECTED



Dark Walnut



Not My Fault
KM5825



GREECIAN WHITE 2"HEXAGON POLISHED



Living Room Finishes

1	Mantel Stain	Dark Walnut
2	Shiplap	KM5825 Not My Fault
3	Tile Around Firebox Opening	MSI Grecian White 2" Hexagon Polished
4	Entry Light	Dement
5	Chandelier	Dement


COLLECTED



Kitchen Finishes


1	Faucet	Delta – Trinsic – Champagne Bronze
2	Island Cabinets	KM5825 Not My Fault
3	Backsplash – Lay in Straight Joint	Speartek White RVAWH2.5X8GL Grout: Frost Trim: White Schluter
4	Granite	Silver Cloud
5	Perimeter Cabinets, Butler’s Pantry Cabinets	KMW46 Picket Fence
6	Pendants	Dement
7	Sconces over Windows	Dement
8	Dining Light	Dement
9	Cabinet Hardware	Collected

COLLECTED



Master Bath

1	Bath Accessories	Collected
2	Plumbing	Delta –Trinsic – Black
3	Granite	Silver Cloud
4	Cabinets	KMW46 Picket Fence
5	Vanity Sconces	Dement
6	Back Wall of Shower	Emser Design Glazed Porcelain – Design Diagram – 9x9 Grout: Avalanche Trim: White Schluter
7	Shower Floor	MSI – Herringbone Mosaic Grout: Avalanche
8	Cabinet Hardware	Collected
9	Main Shower and Tub Tile	Middleton White In Stock Tile Grout: Avalanche Trim: White Schluter



Guest Bath

1	Bath Accessories	Collected
2	Vanity Lights	Dement
3	Plumbing	Delta – Trinsic – Black
4	Granite	Silver Cloud
5	Cabinets	KMW46 Picket Fence
6	Top 12" of Shower	MSI Black and White 1x1 Hexagon Matte Grout: Avalanche Trim: Gold Schluter
7	Main Shower Tile	3x6 Inverted Beveled Subway Tile Grout: Avalanche Trim: Gold Schluter
8	Cabinet Hardware	Collected

COLLECTED



Picket Fence
KMW46

Utility Room

1	Granite	Silver Cloud
2	Utility Cabinets	KMW46 Picket White
3	Cabinet Hardware	Collected



COLLECTED



Mud Room

1	Granite	Silver Cloud
2	Utility Cabinets	KMW46 Picket White
3	Cabinet Hardware	Collected

COLLECTED

Area	Paint Color
Walls & Ceiling	 Rotunda White KM5819
Trim & Cabinets (unless otherwise noted)	 Picket Fence KMW46
Kitchen Island, Fireplace Shiplap	 Not My Fault KM5825
Stain: Beams, mantel	 Dark Walnut

Interior Paint Schedule

COLLECTED

Appliances



GE GGD635HSJSS



GE GGFE26JSMSS



GE GJGS760SELSS






BROAN BPM250




GPEB7227SLSS


KITCHEN CABINET ELEVATIONS SHAKER STYLE CABINETS



FIREPLACE WALL



MASTER BATH VANITIES



GUEST BATH VANITY WALL

